Weekly Control Equipment Maintenance Form

Equipment	Weekly Maintenance Work	Date	Completed By	Corrective Action (if any)
100,000 CFM Scrubber	☑ Clean Packing ☑ Empty and Refill Unit ☑ Clean Probes ☐ Calibrate Probes ☑ Check Pressure Drop ☑ Check Pump and Bearings ☑ Check Motor and Coupling	Week 2/1/10	JM	Check pH probe vs. handheld meter 0.05 variance 1.4" pressure drop
75,000 CFM Scrubber	☑ Clean Packing ☑ Empty and Refill Unit ☑ Clean Probes ☐ Calibrate Probes ☑ Check Pressure Drop ☑ Check Pump and Bearings ☑ Check Motor and Coupling	Week 2/1/10	JM	Check pH probe vs. handheld meter 0.04 variance 2.0" pressure drop
12,000 CFM Venturi Scrubber	☑ Clean Mist Eliminator ☑ Empty and Refill Unit ☑ Check Pressure Drop ☑ Check Pump and Bearings ☑ Check Motor and Coupling	Week 2/1/10	JM	2.0" pressure drop
12,000 CFM Thermal Oxidizer	☑ Check Fan Belts ☑ Check Fan Bearings	Week 2/1/10	JM	

Revised 3/09